

FIG. 1




FIG. 2




FIG. 3






FIG. 4



F1G. 5






FIG. 7








FIG. 8












FIG. 11 (2 og 2)




FIG. 12




FIG. 13





FIG. 14



THEIREST (C) LID	VALUE[dB)	FUNCTION
Thresh.0	-20	ENERGY DETECT
Thresh.1	-17	loc_rcvr_status_OK
Thresh.2	-12	frequency recovery
Thresh.3 (1)	-22.8 (SER=1e-13)	Quality Indicator
Thresh.3 (2)	-22.5 (SER=1e-12)	Quality Indicator
Thresh.3 (3)	-22.0 (SER=1e-11)	Quality Indicator (default)
Thresh.3 (4)	-21.5 (SER=1e-10)	Quality Indicator

FIG. 15





FIG. 16 A






FIG. 16 C






FIG. 16 D








FIG. 16 G









FIG. 17A















FIG. 17 G






FIG. 19A




FIG. 19B




FIG. 20A




FIG. 20B




FIG. 21 A




FIG. 21B




FIG. 22




FIG. 23




FIG. 24

